



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3916-041
Job Sheet 199813



Part No: D3916-041

Job Qty: 12 pcs

Part Name: Rib Assembly



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 9/3/19

Job Tracking No:

Created By: Marie Lajeunesse

Due Date: 9/27/19

Description:

Type: Stock

Note: DWG REV A IPP RevA: New issue DD verified by:EC IPP Rev:B as per dwg revA 10.03.15 verified by:EC

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard Setup Hrs	Run Hrs	Workcenter/Supplier	Lead Time	Sign-off
100	Large Fab - Basket - 1	12 pcs		9/27/19	0.00	5.45	Large Fab - 1		
							Large Fab - 10		
							Large Fab - 2		
							Large Fab - 3		
							Large Fab - 4		
							Large Fab - 5		
							Large Fab - 6		
							Large Fab - 7		
							Large Fab - 8		
							Large Fab - 9		
105	QC 5	12 pcs		9/27/19	0.00	0.00	Large Fab - 11 (Various)		
							QC 5 - 10		
							QC 5 - 12		
							QC 5 - 17		
							QC 5 - 18		
							QC 5 - 19		
							QC 5 - 22		
							QC 5 - 24		
							QC 5 - 3		
							QC 5 - 43		
							QC 5 - 49		
							QC 5 - 51		
							QC 5 - 58		
							QC 5 - 68		
							QC 5 - 9		
							QC 5 - 50		
							QC 5 - 30		
							QC 5 - 40		
							QC 5 - 61		
							QC 5 - 81		
107	Large Fab - Basket - 2 -	12		9/27/19	0.00	6.86	Large Fab - 1 - B4B		



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S214262



Part: D3916-041

Job No: 199813

Serial No/Batch: S214262

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Date: 09/17/19

DAS
43
9-89

B4B

pcs

Large Fab - 10 - B4B

Large Fab - 2 - B4B

Large Fab - 3 - B4B

Large Fab - 4 - B4B

Large Fab - 5 - B4B

Large Fab - 6 - B4B

Large Fab - 7 - B4B

Large Fab - 8 - B4B

Large Fab - 9 - B4B

Large Fab - 11 - B4B

(Various)

QC 5 - 10

QC 5 - 12

QC 5 - 17

QC 5 - 18

QC 5 - 19

QC 5 - 22

QC 5 - 24

QC 5 - 3

QC 5 - 43

QC 5 - 49

QC 5 - 51

QC 5 - 58

QC 5 - 68

QC 5 - 9

QC 5 - 50

QC 5 - 30

QC 5 - 40

QC 5 - 61

QC 5 - 81

QC 10 - 10

QC 10 - 18

QC 10 - 24

QC 10 - 43

QC 10 - 50

QC 10 - 58

QC 10 - 9

Packaging 3 - 1 - B4B

Packaging 3 - 2 - B4B

Packaging 3 - 3 - B4B

Packaging 3 - 4 - B4B

Packaging 3 - 5 - B4B

Packaging 3 - 6 - B4B

Packaging 3 - 7 - B4B

Packaging 3 - 8 - B4B

Packaging 3 - 9 - B4B

Packaging 3 - 10 - B4B

Packaging 3 - 11 - B4B

Packaging 3 - 12 - B4B

Packaging 3 - 13 - B4B

Packaging 3 - 14 - B4B

Packaging 3 - 15 - B4B

Packaging 3 - 16 - B4B

Packaging 3 - 17 - B4B

Packaging 3 - 18 - B4B

Packaging 3 - 19 - B4B

Packaging 3 - 20 - B4B

Packaging 3 - 21 - B4B

Packaging 3 - 22 - B4B

DAS
24
9-89SEP 20 2019
DAS
43
9-89DAS
81
9-89

SEP 20 2019

EL

110 QC 5

12

pcs

9/27/19

0.00 0.00

120 QC 10

12

pcs

9/27/19

0.00 0.00

130 Packaging 3-1 - Stock -
B4B

12

pcs

9/27/19

0.00 0.00

				Packaging 3 - 23 - B4B	
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	
				Packaging 3 - 27 - B4B	
				Packaging 3 - 28 - B4B	
				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
140 QC 21 - SA	12 pcs	9/27/19	0.00 0.00	QC 21 - SA - 21	SEP 20 2019
				QC 21 - SA - 70	
				QC 21 - SA - 53	

Part Op 100 - 1- Cut tube 50" 2- Bend tube with manuel pipe bender as per DT9567 *** Make line at 9.88" and use jig for other
Descriptions: lines, and ensure seam in place on side of tube when bending*** 3- Trim access tube material to finish size as per dwg
D3916 4- Drill and chamfer holes as per dwg D3916-1 using DT9605
105 - (QC5- Inspect part completeness to step on W/O)
107 - (Weld per dwg A/R S.S. rod Batch: M1388111 - weld bushing as per dwg D3916 2- grind welds flush
110 - (QC5- Inspect part completeness to step on W/O)
120 - (QC10- Inspect visual per QSI004- ground welds)
130 - (Identify as per dwg & Stock Location: _____) LOCATION: WA004-5
140 - (QC21- Final Inspection - Work Order Release)

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D3759-1	Bushing	84 pcs (7 ea)	100-Large Fab - Basket - 1	3X S176865 818
M304TS0.750W.049	304 Sq Tube .75X.75X.049W	49.9920 ft (4.166 ea)	100-Large Fab - Basket - 1	5201998

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Large Fab - Basket - 1	D3759-1	84	203	0
	M304TS0.750W.049	50	767	0

Part Specifications

Specifications could not be found.

Plex 9/3/19 9:49 AM Dart.lajeunesse.marie

Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐



Job: _____ Part No. _____		DISPOSITION Rework ☐ ☐ ☐ Scrap ☐ ☐ ☐ Use-as-is ☐ ☐ ☐			DEPARTMENT/PROCESS Skid-tube ☐ ☐ ☐ ☐ ☐ ☐ Machining ☐ ☐ ☐ ☐ ☐ ☐ Large Fab ☐ ☐ ☐ ☐ ☐ ☐ Cross tube ☐ ☐ ☐ ☐ ☐ ☐ Small Fab ☐ ☐ ☐ ☐ ☐ ☐ Finishing ☐ ☐ ☐ ☐ ☐ ☐ Eng. (Non-AW) ☐ ☐ ☐ ☐ ☐ ☐ Prod. Eng. Coord. ☐ ☐ ☐ ☐ ☐ ☐ Rec/Store/Packaging ☐ ☐ ☐ ☐ ☐ ☐ Engineering ☐ ☐ ☐ ☐ ☐ ☐ Water Jet ☐ ☐ ☐ ☐ ☐ ☐ Supplier ☐ ☐ ☐ ☐ ☐ ☐ Quality ☐ ☐ ☐ ☐ ☐ ☐			MRB (QS1042)																											
Date: _____		Sequence #: _____		QTY Affected: _____		Disposition																													
Description Work Order Deviation				Completed By																															
				Lead hand / Supervisor																															
				QC / QA Coordinator																															
Root Cause Operator ☐ ☐ ☐ ☐ ☐ ☐ Manufacturing Process ☐ ☐ ☐ ☐ ☐ ☐ Equip/Tooling ☐ ☐ ☐ ☐ ☐ ☐ Handling/Preservation ☐ ☐ ☐ ☐ ☐ ☐ Material ☐ ☐ ☐ ☐ ☐ ☐ Product Improvement ☐ ☐ ☐ ☐ ☐ ☐ Process Improvement ☐ ☐ ☐ ☐ ☐ ☐ Human Factors ☐ ☐ ☐ ☐ ☐ ☐		FAULT CATEGORY <table border="1"> <tr> <td>Pressure/Forced</td> <td>Contamination</td> <td>Power Loss/Surge</td> <td>Positioned Wrong</td> </tr> <tr> <td>Bending</td> <td>Misaligned/off center</td> <td>Folio/Program</td> <td>Outside Tolerance</td> </tr> <tr> <td>Crushing</td> <td>BOM/Route</td> <td>Grain Direction</td> <td>Drawing</td> </tr> <tr> <td>Cracks</td> <td>Broken/Damage/Defect</td> <td>Weld</td> <td>Finish</td> </tr> <tr> <td>Crimp/Kink/Ripple/Wave/Twist</td> <td>Incomplete/Unclear Instructions</td> <td>Wrong Stock Pulled</td> <td>Part Lost/Missing</td> </tr> <tr> <td>Marks/Chatter</td> <td>Drill Holes</td> <td>Out of Sequence</td> <td>Misread</td> </tr> <tr> <td>Mislabeled</td> <td>Fit/Function</td> <td>Off-set/Set-up</td> <td></td> </tr> </table> Other/Details: _____						Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong	Bending	Misaligned/off center	Folio/Program	Outside Tolerance	Crushing	BOM/Route	Grain Direction	Drawing	Cracks	Broken/Damage/Defect	Weld	Finish	Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled	Part Lost/Missing	Marks/Chatter	Drill Holes	Out of Sequence	Misread	Mislabeled	Fit/Function	Off-set/Set-up	
Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong																																
Bending	Misaligned/off center	Folio/Program	Outside Tolerance																																
Crushing	BOM/Route	Grain Direction	Drawing																																
Cracks	Broken/Damage/Defect	Weld	Finish																																
Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled	Part Lost/Missing																																
Marks/Chatter	Drill Holes	Out of Sequence	Misread																																
Mislabeled	Fit/Function	Off-set/Set-up																																	